

Segue certificato di controllo
Inspection Certificate's continuance

N. 023203 Date 7/03/2014

NOTE - Notes

MECAMAX

Surface quality :(crack test) "class 3"
according to EN 10277-1:2008

We certify hereby, that the above mentioned products are consist-
ent with the order prescriptions.
This certificate was generated by data system acc. to EN 10204,
it is not necessary to be signed for validity.