

**Segue certificato di controllo**  
**Inspection Certificate's continuance**

**N. 023203 Date 7/03/2014**

**NOTE - Notes**

**MECAMAX**

Surface quality :(crack test) "class 3"  
according to EN 10277-1:2008

We certify hereby, that the above mentioned products are consist-  
ent with the order prescriptions.  
This certificate was generated by data system acc. to EN 10204,  
it is not necessary to be signed for validity.